# New 8 GeV Beam Line Technical Systems

David Harding
Proton Driver Meeting
8 December 2004

## Toy WBS

- 1. Magnets
- 2. Vacuum
- 3. Power supplies
- 4. Injection
- 5. Collimation
- 6. 8 GeV Dump
- 7. Debuncher
- 8. Instrumentation
- 9. Controls
- 10. Safety system
- 11. Utilities
- 12. Installation

## 1.1. Magnets – arc dipoles

- Refurbish Main Ring B2 (65 each)
- 6.071 m long, aperture 99 mm x 48 mm
- 125 A for 0.05 T
- 100 W/magnet, no water




## 1.2. Magnets – C Magnets

- First half cell of first arc
- Allows
  - Arc-off running to high power dump
  - Under-accelerated beam out to "dump"
- New design (3 each)
- Same performance specs as B2


#### 1.3. Magnets - quadrupoles

- New design (47 ea)
  - 1.308 m long (same as short MR quads)
  - 79 mm pole tip diameter
  - 41 A for 1.06 T/m ⇒390 W/magnet, nowater



## 1.4. Magnets - Trim dipoles

- Main injector trim dipoles (47 each)
- 0.018 T-m at under 6A



#### 2. Vacuum

- Design for 1x10<sup>-7</sup> torr
- Stainless tube
  - Rectangular in dipoles, 99 mm x 48 mm
  - Round in straights, 144 mm (negotiable)
- Pumps
  - One pump per dipole in arcs
  - One pump per quad in straights
  - Extra pumps at special locations
- Flange connections
- Beam valves, 15-20

#### Vacuum plus

- Collimators in dipoles to dump stripped ions inside magnets
- Add liner at LN<sub>2</sub> temp to reduce stripping??

# 3. Power supplies

- Dipoles
  - One supply
  - 125 A, 75 V (negotiable)
- Arc Quads
  - One supply
  - 41 A, 650 V (negotiable)
- Matching quads
  - Six supplies or trims
  - Comparable currents
- Trim dipoles
  - 47 individual supplies
  - 6 A, 30 V (negotiable)
- Cables, busses

# 4. Injection

- Injection painting into Main Injector will be interesting
- Includes dump

#### 5. Collimation

- Foils
- Dumps

#### 6. 8 GeV Dump

- 2 MW dump at end of linac to take full beam power
- Modeled on Main Injector dump
- Included elsewhere
  - Dumps for collimation system
  - Dump for unstripped beam on injection

#### 7. Debuncher

Nothing to report

#### 8. Instrumentation

- BPM system at quads
- Beam loss monitors everywhere
- Torroids start, middle, end
- Profile monitors start, middle, end, arcs
- Longitudinal profile monitor(s)
- Cables

#### 9. Controls

- Yes
- Standard
- Cables

# 10. Safety system

- Yes!
- Standard

#### 11. Utilities

- LCW
  - Needed for power supplies
  - Needed for dumps

#### 12. Installation

- Stands
  - Magnets
  - Vacuum
  - Instrumentation
- Placement
- Alignment
- Coordination